

SMOG CHECK ADVISORY

Official Publication of the California Department of Consumer Affairs/Bureau of Automotive Repair

February 2000

Governor Davis Names New BAR Chief

overnor Gray Davis announced the appointment of Douglas E. Laue as Chief, Bureau of Automotive Repair on January 18th.

Mr. Laue has been employed with the Department of Consumer Affairs in various positions since 1975. He has held the position of **Deputy Executive** Director for the California Medical Board since 1993. From 1991 to 1993. he served as the Assistant Chief of Information Systems for the



Department of Consumer Affairs. Prior to this, he served for 10 years as a Deputy Chief of the Bureau of Automotive Repair. He earned a Bachelor of

Arts degree from the University of California, Berkeley.

Patrick Dorais, who had been Acting Chief since last May, will be returning to his former position as BAR's Deputy Chief. Richard Mundy, who had been Acting Deputy Chief during that time, will now resume his previous BAR duties as Deputy Chief of Enforcement.

BAR and ARB Officials Host Smog Check Workshop in Tijuana, Mexico

alifornia's Smog Check Program was the focus of a two-day workshop for Mexican government officials and air quality experts on January 11 and 12 in Tijuana, Mexico, and Chula Vista. Presentations were provided by the following workshop sponsors: the California Environmental Protection Agency, Air Resources Board, and Department of Consumer Affairs/Bureau of Automotive Repair (DCA/BAR) The workshop was requested by Baja officials who plan to implement a vehicle inspection program by the end of this year.

After an overview of the Smog Check Program by then Acting BAR Chief Patrick Dorais, BAR

Workshop (continued page 3)

In This Issue . . .

Governor Davis Names New BAR Chief 1
BAR and ARB Officials Host Smog Check Workshop in Tijuana. Mexico 1
Demystifying the Test-Only Process 1
SNAPSHOT
California Ahead of Feds on SUV Emission Standards
Historical Test Data Accessible on EIS Machines
Census 2000 4
The Bottom Line 4
Tech Tips & Causes of Disciplinary Actions are Top Reader Survey Requests
Correction 5
Disciplinary Actions 6
Voided Warranty on Improper Cat Replacement?6
CAP Pays Off With More Effective Repairs
Smog Check Station Citations 7
Little Scoops 8

Demystifying the Test-Only Process

ome Smog Check technicians and shop owners may be confused about the process used to determine which vehicles are included in the category called High Emitter Profile (HEP) and then directed to Test-Only stations for testing.

"Technicians have no control over which vehicles are selected to be sent to a Test-Only station as possible HEP vehicles," according to BAR Engineering Manager David Amlin. "We send vehicles that match our HEP criteria to Test-Only, and pretesting those vehicles cannot prevent the referral in the current or future years."

Pretesting a non-Test-Only directed vehicle may possibly help it avoid failure as a Gross Polluter and a certification test at Test-Only, but it does not mean the vehicle will avoid Test-Only referral in its next cycle.

To comply with the mandates of the federal Clean Air Act, BAR directs vehicles located in the Enhanced Areas of the state to Test-Only stations to ensure that a *minimum* of 15 percent are inspected at Test-Only stations.

Prior to selecting vehicles through the HEP for inspection at Test-Only stations, 2 percent of vehicles from the entire Enhanced Area fleet are randomly selected and sent to Test-Only stations as a check to evaluate the overall effectiveness of the Smog Check Program.

HEP referrals to Test-Only stations are made based on a set of data developed from several sources, including:

- The state Vehicle Information Database (VID), which collects the results of Smog Checks done on all vehicles. Those results are transferred by modem by the analyzers at Smog Check stations statewide.
- Smog Check inspection results collected before the VID was established.
- General vehicle data such as make, model year, vehicle miles traveled, and engine family.

Test-Only (continued page 4)

SNAPSHOT

Here are the Smog Check testing and repair statistics for the months of November and December 1999. As always, the "Tests Conducted" data represents all Acceleration Simulation Mode (ASM) and Two-Speed Idle (TSI) tests performed on vehicles by Smog Check stations statewide, with the number of certificates that resulted from these tests shown under "Certificates Issued." The remaining data represent only ASM and TSI first (initial) tests performed on vehicles. The difference between Enhanced and Basic/Change of Ownership (COO) Areas of the state is also shown.

Program Notume		NOVEMBER	DECEMBER
Vehicles Tested	9	004 544 #	0.0000.4
Enhanced Basic/COO 262,950 265,357 Vehicles Failed 82,621 (11.3%) 78,600 (10.8%)			
Basic/COO 262,950 265,357			
Vehicles Failed			
Enhanced 56,326 (13.9%) 61,551 (13.3%) Basic/COO 747,366 735,060 Certificates Issued 747,366 735,060 Type of Failure Talipipe 60,070 (8.2%) 46,378 (10.0%) 10,477 (3.9%) 65,826 (7.8%) 10,477 (3.9%) 675,826 (1.8%) 46,378 (10.0%) 10,447 (3.9%) 676,826 (1.8%) 10,447 (3.9%) 676,826 (1.8%) 10,447 (3.9%) 676,826 (1.8%) 10,447 (3.9%) 676,826 (1.8%) 10,447 (3.9%) 676,826 (1.8%) 10,447 (3.9%) 676,826 (1.8%) 10,447 (3.9%) 676,826 (1.8%) 10,447 (3.9%) 676,826 (1.8%) 10,447 (3.9%) 676,826 (1.8%) 10,447 (3.9%) 676,826 (1.8%) 10,447 (3.9%) 676,826 (1.8%) 10,447 (3.9%) 676,826 (1.8%) 10,447 (3.9%) 676,826 (1.8%) 10,447 (3.9%) 676,826 (1.8%)			
Certificates Issued 747,366 735,060 Type of Failure Tailpipe 60,070 (8,2%) 46,378 (10,0%) 8asic/COO 10,597 (4,0%) 10,447 (3,9%) 25,988 (3,6%) ** Enhanced 22,998 (4,9%) 21,508 (4,6%) 8asic/COO 4,837 (1,7%) 4,480 (1,8%) 4,485 (1,			
Type of Failure	Basic/COO	17,295 (6.6%)	17,106 (6.5%)
Talipipe Enhanced 49,464 (10.5%) Basic/COO 10.597 (4.0%) Basic/COO 10.597 (4.0%) Basic/COO 10.597 (4.0%) Basic/COO 4,837 (1.7%) Basic/COO 1,837 (1.7%) Basic/COO 1,837 (1.7%) Basic/COO 2,25% 14,0% Basic/COO 2,25% 14,0% Basic/COO 2,25% 14,0% Basic/COO 3,3%) Basic/COO 3,3% 3,143 (7.0%) Basic/COO 8,883 (3.5%) Basic/COO 8,883 (3.5%) Basic/COO 8,883 (3.5%) Basic/COO 1,152 (3.9%) Basic/COO 1,15	Certificates Issued	747,366	735,060
Enhanced Basic/COO 10.597 (4.0%) 10.447 (3.9%) Basic/COO 10.597 (4.0%) 10.447 (3.9%) Gross Polluters 27.828 (3.8%) ** 25.988 (3.6%) ** Enhanced 22.985 (4.9%) 21.508 (4.6%) Basic/COO 4,837 (1.7%) 4,480 (1.8%) Visual 17.999 (2.5%) 16.637 (2.3%) Enhanced 15.367 (3.3%) 14.074 (3.0%) Basic/COO 2,632 (1.0%) 2,563 (1.0%) Functional 42.026 (5.7%) 40.262 (5.5%) Enhanced 33.143 (7.0%) 31.536 (6.8%) Basic/COO 8,883 (3.5%) 8,726 (3.3%) Enhanced 33.143 (7.0%) 31.536 (6.8%) Basic/COO 10.182 (3.9%) 9,887 (5.7%) GSGR Enhanced 24.432 (9.8%) 22.292 (9.2%) Basic/COO 10.182 (3.9%) 9,887 (5.7%) GSGR Enhanced 11.543 (10.7%) 11.004 (10.3%) Basic/COO 3,946 (8.0%) 4,035 (8.1%) GPC Enhanced 2.213 (13.5%) 2,163 (13.3%) Basic/COO 2,808 (7.0%) 2,773 (7.0%) Test-Only Enhanced 2.749 (28.3%) 25.451 (27.2%) Basic/COO 251 (17.8%) 245 (18.1%) By Type High Emitter Profile (HEP) 18,400 (38.5%) 17,748 (36.2%) Random 2% 1,819 (29.7%) 1,773 (29.2%) Volunteers 6,540 (6.1%) 6,157 (15.6%) Average Reported Repair Casts Vehicles Repaired Assistance Program Vehicles Reciving Repair Assistance Vehicles Reciving Repair Assistance Vehicles Reciving Repair Assistance Vehicles Retired 553 134 *** Includes consumer co-psy.	Type of Failure		
Basic/COO 10,597 (4.0%) 10,447 (3.9%) Gross Pollulers 27,828 (3.8%)** 25,988 (3.6%)** Enhanced 22,985 (4.9%) 21,508 (4.6%) Basic/COO 4,837 (1.7%) 4,480 (1.8%) Visual 17,999 (2.5%) 16,637 (2.3%) Enhanced 15,367 (3.3%) 14,074 (3.0%) Basic/COO 2,632 (1.0%) 2,563 (1.0%) Functional 42,026 (5.7%) 40,262 (5.5%) Enhanced 33,143 (7.0%) 31,536 (6.8%) Basic/COO 8,883 (3.5%) 8,726 (3.3%) Fallure by Sation Type 7 Test & Repair 24,432 (9.8%) 22,292 (9.2%) Basic/COO 10,182 (3.9%) 22,292 (9.2%) Basic/COO 2,808 (7.0%) 2,773 (7.0%) Test-Only 2 2,163 (13.3%) Basic/COO 2,504 (28.3%) 2,545 (12.2%) Basic/COO </td <td>Tailpipe</td> <td></td> <td>56,826 (7.8%)</td>	Tailpipe		56,826 (7.8%)
Cross Polluters			
Enhanced 22,985 (4,9%) 21,508 (4,6%) 8asic/COO 4,837 (1.7%) 4,480 (1.8%) Visual 17,999 (2.5%) 16,637 (2.3%) 14,074 (3.0%) 8asic/COO 2,632 (1.0%) 2,563 (1.0%) Functional 42,026 (5.7%) 40,262 (5.5%) 8asic/COO 8,8483 (3.5%) 8,726 (3.3%) 8,726 (3.3%) Failure by Station Type Test & Repair Enhanced 24,432 (9,8%) 8,726 (3.3%) Failure by Station Type Test & Repair Enhanced 24,432 (9,8%) 9,887 (5.7%) GSGR Enhanced 11,543 (10.7%) 11,004 (10.3%) 8,726 (3.3%) Failure by Station Type Test & Repair Enhanced 11,543 (10.7%) 11,004 (10.3%) 8,726 (3.3%) Failure by Station Type Test & Repair Enhanced 2,213 (13.5%) 2,163 (13.3%) 8,726 (3.3%) Financed 2,213 (13.5%) 2,163 (13.3%) 8,726 (3.3%) Failure by Station Type Test Conly Enhanced 26,749 (28.3%) 2,773 (7.0%) Test Conly Enhanced 26,749 (28.3%) 2,773 (7.0%) Test Conly Enhanced 26,749 (28.3%) 245 (18.1%) Basic/COO 251 (17.8%) 245 (18.1%) By Type High Emitter Profile (HEP) 18,400 (38.5%) 17,748 (36.2%) Random 2% 1,819 (29.7%) 1,773 (29.2%) Volunteers 6,540 (16.1%) 40,773 (29.2%) Volunteers 6,540 (16.1%) 5,879 Average Reported Repair Cast Vehicles Repair Stations \$ 199 \$ 1101 GSGR Stations \$ 109 \$ 1111 GSGR Stations \$ 109 \$ 1111 GSGR Stations \$ 195 \$ 197 Consumer Assistance Vehicles \$ 454 *** \$ 437 *** Enhanced Areas \$ 128 \$ 130 Sasci-COO Areas \$ 114 \$ 120 Consumer Assistance Program Vehicles Receiving Repair Assistance Vehicles Receiving Repair Assistance Vehicles consumer con			
Basic/COO			
Visual 17,999 (2.5%) 16,637 (2.3%) Enhanced 15,367 (3.3%) 14,074 (3.0%) Basic/COO 2,632 (1.0%) 2,563 (1.0%) Functional 42,026 (5.7%) 40,262 (5.5%) Enhanced 33,143 (7.0%) 31,536 (6.8%) Basic/COO 8,883 (3.5%) 8,726 (3.3%) Failure by Station Type Test & Repair Enhanced 24,432 (9.8%) 22,292 (9.2%) Basic/COO 10,182 (3.9%) 9,887 (5.7%) GSGR Enhanced 11,543 (10.7%) 11,004 (10.3%) Basic/COO 3,946 (8.0%) 4,035 (8.1%) GPC Enhanced 2,213 (13.5%) 2,163 (13.3%) Basic/COO 2,808 (7.0%) 2,773 (7.0%) Test-Only Enhanced 26,749 (28.3%) 25,451 (27.2%) Basic/COO 2,808 (7.0%) 2,773 (7.0%) Basic/COO 2,501 (17.8%) 245 (18.1%) Basic/COO 2,501 (17.8%) 245 (18.1%) Basic/COO 2,502 (17.8%) 1,7748 (36.2%)			
Enhanced 15,367 (3,3%) 14,074 (3,0%) Basic/COO 2,632 (1,0%) 2,563 (1,0%) Functional 42,026 (5,7%) 40,262 (5,5%) Enhanced 33,143 (7,0%) 31,536 (8,8%) Basic/COO 8,883 (3,5%) 8,726 (3,3%) Falture by Station Type Test & Repair Enhanced 24,432 (9,8%) 22,292 (9,2%) Basic/COO 10,182 (3,9%) 9,887 (5,7%) GSGR Enhanced 11,543 (10,7%) 11,004 (10,3%) Basic/COO 3,946 (8,0%) 4,035 (8,1%) GPC Enhanced 2,213 (13,5%) 2,163 (13,3%) Basic/COO 2,808 (7,0%) 2,773 (7,0%) Test-Only Enhanced 26,749 (28,3%) 2,163 (13,3%) Basic/COO 2,508 (7,0%) 2,773 (7,0%) Test-Only Enhanced 26,749 (28,3%) 25,451 (27,2%) Basic/COO 2,51 (17,8%) 245 (18,1%) By Type High Emitter Profile (HEP) 18,400 (38,5%) 11,773 (29,2%) Volunteers 6,540 (16,1%) 6,157 (15,6%) Average Reported Repair Costs Vehicles Repaired 57,949 55,879 Average Cost (statewide) 5123 \$126 Test & Repair Stations \$99 \$101 GPC Stations \$109 \$111 GPC Stations \$100 \$110 GPC Stations \$100 \$100 GPC Stations \$100 \$100 GPC Stations \$100 \$100 GPC Stations \$100 \$100 GP		· · · · · · · · · · · · · · · · · · ·	
Functional			
Enhanced 33,143 (7.0%) 8,883 (3.5%) 8,726 (3.3%) Failure by Sation Type Test & Repair Enhanced 24,432 (9.8%) 22,292 (9.2%) 8asic/COO 10,182 (3.9%) 9,887 (5.7%) GSGR Enhanced 11,543 (10.7%) 11,004 (10.3%) 8asic/COO 3,946 (8.0%) 4,035 (8.1%) GPC Enhanced 2,213 (13.5%) 2,163 (13.3%) 8asic/COO 2,808 (7.0%) 2,773 (7.0%) Test-Only Enhanced 26,749 (28.3%) 2,163 (13.3%) 8asic/COO 251 (17.8%) 245 (18.1%) Basic/COO 3,946 (8.0%) 4,035 (8.1%) Fest-Only Enhanced 26,749 (28.3%) 2,163 (13.3%) 8asic/COO 251 (17.8%) 2,163 (13.3%) 8asic/COO 3,181 (10.1%) 1,773 (29.2%	Basic/COO	2,632 (1.0%)	2,563 (1.0%)
Basic/COO 8,883 (3.5%) 8,726 (3.3%) Fallure by Nation Type Test & Repair Enhanced 24,432 (9.8%) 22,292 (9.2%) Basic/COO 10,182 (3.9%) 9,887 (5.7%) GSGR Enhanced 11,543 (10.7%) 11,004 (10.3%) Basic/COO 3,946 (8.0%) 4,035 (8.1%) GPC Enhanced 2,213 (13.5%) 2,163 (13.3%) Basic/COO 2,808 (7.0%) 2,773 (7.0%) Test-Only Enhanced 26,749 (28.3%) 25,451 (27.2%) Basic/COO 25,808 (7.0%) 25,451 (27.2%) Basic/COO 25,1 (17.8%) 245 (18.1%) By Type High Emitter Profile (HEP) 18,400 (38.5%) 17,748 (36.2%) Random 2% 1,819 (29.7%) 1,773 (29.2%) Volunteers 6,540 (16.1%) 6,157 (15.6%) Average Reported Repair Costs Vehicles Repaired 57,949 55,879 Average Cost (statewide) \$123 \$126 Test & Repair Stations \$99 \$101 GSGR Stations \$109 \$111 GPC Stations \$195 \$197 Consumer Assistance Vehicles \$454*** Enhanced Areas \$128 \$130 Basic/COO Areas \$114 \$120 Consumer Assistance Program Vehicles Reciving Repair Assistance Vehicles Retired 53 134 ***Includes consumer co-pay. Repair Cost Waivers Issued 97 105			
Failure by Station Type Test & Repair Enhanced 24,432 (9.8%) 22,292 (9.2%) Basic/COO 10,182 (3.9%) 9,887 (5.7%)			
Test & Repair Enhanced 24,432 (9.8%) 9,887 (5.7%) GSGR Enhanced 11,543 (10.7%) 11,004 (10.3%) Basic/COO 3,946 (8.0%) 4,035 (8.1%) GPC Enhanced 2,213 (13.5%) 2,163 (13.3%) Basic/COO 2,808 (7.0%) 2,773 (7.0%) Test-Only Enhanced 26,749 (28.3%) 25,451 (27.2%) Basic/COO 251 (17.8%) 245 (18.1%) By Type High Emitter Profile (HEP) 18,400 (38.5%) 17,748 (36.2%) Random 2% 1,819 (29.7%) 1,773 (29.2%) Volunteers 6,540 (16.1%) 6,157 (15.6%) Average Reported Repair Costs Vehicles Repaired SF,949 55,879 Average Cost (statewide) \$ 123 \$ 126 Test & Repair Stations \$ 99 \$ 101 GSGR Statlons \$ 109 \$ 111 GPC Stations \$ 109 \$ 111 GPC Stations \$ 195 \$ 197 Consumer Assistance Vehicles \$ 454 *** \$ 437 *** Enhanced Areas \$ 128 Basic/COO Areas \$ 114 \$ 120 Consumer Assistance Program Vehicles Receiving Repair Assistance Vehicles Reciving Repair Assistance Vehicles Retired 53 134 *** Subset of tallpipe failures Includes consumer co-pay. Repair Cost Waivers Issued		6,883 (3.5%)	6,720 (3.3%)
Enhanced Basic/COO 10,182 (3,9%) 9,887 (5,7%) GSGR Enhanced 11,543 (10,7%) 11,004 (10,3%) Basic/COO 3,946 (8,0%) 4,035 (8,1%) GPC Enhanced 2,213 (13,5%) 2,163 (13,3%) Basic/COO 2,808 (7,0%) 2,773 (7,0%) Test-Only Enhanced 26,749 (28,3%) 25,451 (27,2%) Basic/COO 251 (17,8%) 245 (18,1%) By Type High Emitter Profile (HEP) 18,400 (38,5%) 17,748 (36,2%) Random 2% 1,819 (29,7%) 1,773 (29,2%) Volunteers 6,540 (16,1%) 6,157 (15,6%) Average Reported Repair Costs Vehicles Repaired 57,949 55,879 Average Cost (statewide) \$ 123 \$ 126 Test & Repair Stations \$ 99 \$ 101 GSGR Stations \$ 109 \$ 111 GGCR Stations \$ 195 \$ 119 Consumer Assistance Vehicles \$ 454 *** \$ 437 *** Enhanced Areas \$ 128 Basic/COO Areas \$ 114 \$ 120 Consumer Assistance Program Vehicles Receiving Repair Assistance Vehicles Receiving Repair Assistance Vehicles Receiving Repair Assistance Vehicles Retired 53 134 *** Includes consumer co-pay. Repair Cost Waivers Issued			
Basic/COO 10,182 (3,9%) 9,887 (5,7%) GSGR Enhanced 11,543 (10.7%) 11,004 (10.3%) Basic/COO 3,946 (8.0%) 4,035 (8.1%) GPC Enhanced 2,213 (13.5%) 2,163 (13.3%) Basic/COO 2,808 (7.0%) 2,773 (7.0%) Test-Only Enhanced 26,749 (28.3%) 25,451 (27.2%) Basic/COO 251 (17.8%) 245 (18.1%) By Type High Emitter Profile (HEP) 18,400 (38.5%) 17,748 (36.2%) Random 2% 1,819 (29.7%) 1,773 (29.2%) Volunteers 6,540 (16.1%) 6,157 (15.6%) Average Reported Repair Costs Vehicles Repaired 57,949 55,879 Average Cost (statewide) \$ 123 \$ 126 Test & Repair Stations \$ 99 \$ 101 GSGR Stations \$ 109 \$ 111 GPC Stations \$ 109 \$ 111 GPC Stations \$ 109 \$ 111 GPC Stations \$ 195 Consumer Assistance Vehicles \$ 454 *** \$ 437 *** Enhanced Areas \$ 128 \$ 130 Basic/COO Areas \$ 114 \$ 120 Consumer Assistance Program Vehicles Receiving Repair Assistance Vehicles Retired 53 134 **** Includes consumer co-pay.	•	24.432 (9.8%)	22.292 (9.2%)
Enhanced Basic/COO 3,946 (8.0%) 4,035 (8.1%) GPC Enhanced 2,213 (13.5%) 2,163 (13.3%) Basic/COO 2,808 (7.0%) 2,773 (7.0%) Test-Only Enhanced 26,749 (28.3%) 25,451 (27.2%) Basic/COO 251 (17.8%) 245 (18.1%) By Type High Emitter Profile (HEP) 18,400 (38.5%) 17,748 (36.2%) Random 2% 1,819 (29.7%) 1,773 (29.2%) Volunteers 6,540 (16.1%) 6,157 (15.6%) Average Reported Repair Costs Vehicles Repaired 57,949 55,879 Average Cost (statewide) \$ 123 \$ 126 Test & Repair Stations \$ 99 \$ 101 GSGR Stations \$ 109 \$ 111 GPC Stations \$ 109 \$ 111 GPC Stations \$ 195 \$ 197 Consumer Assistance Vehicles \$ 454 *** \$ 437 *** Enhanced Areas \$ 128 \$ 130 Basic/COO Areas \$ 114 \$ 120 Consumer Assistance Program Vehicles Receiving Repair Assistance Vehicles Receiving Repair Assistance Vehicles Receiving Repair Assistance Vehicles Retired 53 134 *** Subset of tailpipe failures. *** Includes consumer co-pay. Repair Cost Waivers Issued			
Basic/COO 3,946 (8.0%) 4,035 (8.1%) GPC Enhanced 2,213 (13.5%) 2,163 (13.3%) Basic/COO 2,808 (7.0%) 2,773 (7.0%) Test-Only Enhanced 26,749 (28.3%) 25,451 (27.2%) Basic/COO 251 (17.8%) 245 (18.1%) By Type High Emitter Profile (HEP) 18,400 (38.5%) 17,748 (36.2%) Random 2% 1,819 (29.7%) 1,773 (29.2%) Volunteers 6,540 (16.1%) 6,157 (15.6%) Average Reported Repair Costs Vehicles Repaired 57,949 55,879 Average Cost (statewide) 123 126 Test & Repair Stations 99 \$101 GSGR Stations \$109 \$111 GPC Stations \$109 \$111 GPC Stations \$195 \$197 Consumer Assistance Vehicles \$454 *** \$437 *** Enhanced Areas \$128 \$130 Basic/COO Areas \$114 \$120 Consumer Assistance Program Vehicles Receiving Repair Assistance Vehicles Receiving Repair Assistance Vehicles Receiving Repair Assistance Vehicles Retired 53 134 *** Includes consumer co-pay. Repair Cost Waivers Issued	GSGR		
Care			
Enhanced Basic/COO 2,808 (7.0%) 2,163 (13.3%) 2,773 (7.0%) Test-Only Enhanced 26,749 (28.3%) 25,451 (27.2%) Basic/COO 251 (17.8%) 245 (18.1%) By Type High Emitter Profile (HEP) 18,400 (38.5%) 17,748 (36.2%) Random 2% 1,819 (29.7%) 1,773 (29.2%) Volunteers 6,540 (16.1%) 6,157 (15.6%) Average Reported Repair Costs Vehicles Repaired 57,949 55,879 Average Cost (statewide) \$ 123 \$ 126 Test & Repair Stations \$ 99 \$ 101 GSGR Stations \$ 109 \$ 111 GPC Stations \$ 109 \$ 111 GPC Stations \$ 195 \$ 197 Consumer Assistance Vehicles \$ 454 *** \$ 437 *** Enhanced Areas \$ 128 \$ 130 Basic/COO Areas \$ 114 \$ 120 Consumer Assistance Program Vehicles Receiving Repair Assistance 614 621 ** Subset of tailpipe failures. Subset of tailpipe failures. Includes consumer co-pay. Repair Cost Waivers Issued 97 105		3,946 (8.0%)	4,035 (8.1%)
Basic/COO 2,808 (7.0%) 2,773 (7.0%) Test-Only Enhanced		2 212 (12 5%)	2 162 (12 2%)
Test-Only			
Enhanced Basic/COO 26,749 (28.3%) 25,451 (27.2%) Basic/COO 251 (17.8%) 245 (18.1%) By Type 8 High Emitter Profile (HEP) 18,400 (38.5%) 17,748 (36.2%) Random 2% 1,819 (29.7%) 1,773 (29.2%) Volunteers 6,540 (16.1%) 6,157 (15.6%) Average Reported Repair Costs 8 8 Vehicles Repaired 57,949 55,879 Average Cost (statewide) \$ 123 \$ 126 Test & Repair Stations \$ 99 \$ 101 GSGR Stations \$ 109 \$ 111 GPC Stations \$ 195 \$ 197 Consumer Assistance Vehicles \$ 454 *** \$ 437 *** Enhanced Areas \$ 128 \$ 130 Basic/COO Areas \$ 114 \$ 120 Consumer Assistance Program ** Includes multiple tests on same vehicle. Vehicles Receiving Repair Assistance 614 621 ** Subset of tailpipe failures. Vehicles Retired 53 134 *** Includes consumer co-pay. Repair Cost Waivers Issued 97 105	Test-Only	,	
By Type High Emitter Profile (HEP) 18,400 (38.5%) (38.5%) 17,748 (36.2%) Random 2% Volunteers 1,819 (29.7%) (1,773 (29.2%) 1,773 (29.2%) Volunteers 6,540 (16.1%) 6,157 (15.6%) Average Reported Repair Costs Vehicles Repaired 57,949 55,879 Average Cost (statewide) \$ 123 \$ 126 Test & Repair Stations \$ 99 \$ 101 GSGR Stations \$ 109 \$ 111 GPC Stations \$ 195 \$ 197 Consumer Assistance Vehicles \$ 454 **** \$ 437 *** Enhanced Areas \$ 128 \$ 130 Basic/COO Areas \$ 114 \$ 120 Consumer Assistance Program * Includes multiple tests on same vehicle. Vehicles Receiving Repair Assistance 614 621 same vehicle. Vehicles Retired 53 134 *** Includes consumer co-pay. Repair Cost Waivers Issued 97 105	•	26,749 (28.3%)	· · · · · · · · · · · · · · · · · · ·
High Emitter Profile (HEP) 18,400 (38.5%) 17,748 (36.2%) Random 2% 1,819 (29.7%) 1,773 (29.2%) Volunteers 6,540 (16.1%) 6,157 (15.6%) Average Reported Repair Costs Vehicles Repaired 57,949 55,879 Average Cost (statewide) \$ 123 \$ 126 Test & Repair Stations \$ 99 \$ 101 GSGR Stations \$ 109 \$ 111 GPC Stations \$ 195 \$ 197 Consumer Assistance Vehicles \$ 454 *** \$ 437 *** Enhanced Areas \$ 128 \$ 130 Basic/COO Areas \$ 114 \$ 120 Consumer Assistance Program Vehicles Receiving Repair Assistance 614 Vehicles Retired 53 134 *** Includes multiple tests on same vehicle. *** Subset of tailpipe failures. Includes consumer co-pay. Repair Cost Waivers Issued		251 (17.8%)	245 (18.1%)
Random 2% 1,819 (29.7%) 1,773 (29.2%) Volunteers 6,540 (16.1%) 6,157 (15.6%) Average Reported Repair Costs Vehicles Repaired 57,949 55,879 Average Cost (statewide) \$ 123 \$ 126 Test & Repair Stations \$ 99 \$ 101 GSGR Stations \$ 109 \$ 111 GPC Stations \$ 195 \$ 197 Consumer Assistance Vehicles \$ 454 *** \$ 437 *** Enhanced Areas \$ 128 \$ 130 Basic/COO Areas \$ 114 \$ 120 Consumer Assistance Program * Includes multiple tests on same vehicle. Vehicles Receiving Repair Assistance 614 621 ** Subset of tailpipe failures. Vehicles Retired 53 134 *** Includes consumer co-pay. Repair Cost Waivers Issued 97 105		19 400 (29 5%)	17 749 (26 2%)
Volunteers 6,540 (16.1%) 6,157 (15.6%) Average Reported Repair Costs Vehicles Repaired 57,949 55,879 Average Cost (statewide) \$ 123 \$ 126 Test & Repair Stations \$ 99 \$ 101 GSGR Stations \$ 109 \$ 111 GPC Stations \$ 195 \$ 197 Consumer Assistance Vehicles \$ 454 *** \$ 437 *** Enhanced Areas \$ 128 \$ 130 Basic/COO Areas \$ 114 \$ 120 Consumer Assistance Program * Includes multiple tests on same vehicle. Vehicles Receiving Repair Assistance 614 621 ** Subset of tailpipe failures. Vehicles Retired 53 134 *** Includes consumer co-pay. Repair Cost Waivers Issued 97 105	` '		
Vehicles Repaired 57,949 55,879 Average Cost (statewide) \$ 123 \$ 126 Test & Repair Stations \$ 99 \$ 101 GSGR Stations \$ 109 \$ 111 GPC Stations \$ 195 \$ 197 Consumer Assistance Vehicles \$ 454 *** \$ 437 *** Enhanced Areas \$ 128 \$ 130 Basic/COO Areas \$ 114 \$ 120 Consumer Assistance Program * Includes multiple tests on same vehicle. Vehicles Receiving Repair Assistance 614 621 ** Subset of tailpipe failures. Vehicles Retired 53 134 *** Includes consumer co-pay. Repair Cost Waivers Issued 97 105	Volunteers		· · · · · · · · · · · · · · · · · · ·
Average Cost (statewide) \$ 123 \$ 126 Test & Repair Stations \$ 99 \$ 101 GSGR Stations \$ 109 \$ 111 GPC Stations \$ 195 \$ 197 Consumer Assistance Vehicles \$ 454 *** \$ 437 *** Enhanced Areas \$ 128 \$ 130 Basic/COO Areas \$ 114 \$ 120 Consumer Assistance Program Vehicles Receiving Repair Assistance 614 621 ** Subset of tailpipe failures. Vehicles Retired 53 134 *** Includes consumer co-pay. Repair Cost Waivers Issued	Average Reported Repair Costs		
Test & Repair Stations \$ 99 \$ 101 GSGR Stations \$ 109 \$ 111 GPC Stations \$ 195 \$ 197 Consumer Assistance Vehicles \$ 454 *** \$ 437 *** Enhanced Areas \$ 128 \$ 130 Basic/COO Areas \$ 114 \$ 120 Consumer Assistance Program Vehicles Receiving Repair Assistance 614 621 ** Subset of tailpipe failures. Vehicles Retired 53 134 *** Includes consumer co-pay. Repair Cost Waivers Issued	Vehicles Repaired	57,949	55,879
GSGR Stations \$ 109 \$ 111 GPC Stations \$ 195 \$ 197 Consumer Assistance Vehicles \$ 454 *** \$ 437 *** Enhanced Areas \$ 128 \$ 130 Basic/COO Areas \$ 114 \$ 120 Consumer Assistance Program Vehicles Receiving Repair Assistance 614 621 same vehicle. ** Subset of tailpipe failures. Vehicles Retired 53 134 *** Includes consumer co-pay. Repair Cost Waivers Issued	Average Cost (statewide)	\$ 123	\$ 126
GPC Stations \$ 195 \$ 197 Consumer Assistance Vehicles \$ 454 *** \$ 437 *** Enhanced Areas \$ 128 \$ 130 Basic/COO Areas \$ 114 \$ 120 Consumer Assistance Program Vehicles Receiving Repair Assistance 614 621 ** Subset of tailpipe failures. Vehicles Retired 53 134 *** Includes consumer co-pay. Repair Cost Waivers Issued 97 105	•	· ·	
Consumer Assistance Vehicles \$ 454 *** \$ 437 *** Enhanced Areas \$ 128 \$ 130 Basic/COO Areas \$ 114 \$ 120 Consumer Assistance Program Vehicles Receiving Repair Assistance 614 621 ** Subset of tailpipe failures. Vehicles Retired 53 134 *** Includes consumer co-pay. Repair Cost Waivers Issued 97 105			
Enhanced Areas \$ 128 \$ 130 Basic/COO Areas \$ 114 \$ 120 Consumer Assistance Program Vehicles Receiving Repair Assistance \$ 614 \$ 621 \$ same vehicle. Vehicles Retired \$ 53 \$ 134 \$ *** Includes consumer co-pay. Repair Cost Waivers Issued \$ 97 \$ 105			
Basic/COO Areas \$ 114 \$ 120 Consumer Assistance Program Vehicles Receiving Repair Assistance			
Consumer Assistance Program* Includes multiple tests onVehicles Receiving Repair Assistance614621same vehicle.Vehicles Retired53134*** Subset of tailpipe failures.Repair Cost Waivers Issued97105			
Vehicles Receiving Repair Assistance 614 621 same vehicle. Vehicles Retired 53 134 *** Includes consumer co-pay. Repair Cost Waivers Issued 97 105		ψιιτ	
Vehicles Retired 53 134 *** Includes consumer co-pay. Repair Cost Waivers Issued 97 105		614	621 same vehicle.
Repair Cost Waivers Issued 97 105	• '		^^ Subset of tailpipe failures.
			includes consumer co-pay.
	•		

2

California Ahead of Feds on SUV Emission Standards

resident Clinton's announcement in December 1999 of new pollution control regulations, which for the first time applied to the popular SUVs and minivans, should have no effect in California since the state's Air Resources Board (ARB) has already enacted even tougher standards with a faster timetable.

The federal Environmental Protection Agency (EPA) regulations, directed at automakers, will go into effect with the 2004 model-year vehicles. The new standards will progressively cut oxides of nitrogen (NOx) emissions from 0.4 grams per mile for cars (and somewhat higher for SUVs) to 0.07 for cars and most SUVs by the year 2007. However, California's current standard for NOx emissions is 0.2 grams per mile. Already enacted changes will reduce that limit to 0.05 for passenger vehicles beginning with the 2004 models and 0.07 for SUVs . . . three years sooner than the new federal standard. "California has always been ahead of the federal government in emission standards and it remains so," said Richard Varenchik, a spokesperson for the California ARB.

SUVs, pickup trucks, and minivans are traditionally classified as light trucks and, therefore, are subject to less stringent emission regulations. These vehicles account for nearly half of the new vehicles sold in the United States. "Working closely with industry, we will ensure both the freedom of American families to drive the vehicles of their choice and the right of American children to breathe clean, healthy air," said Clinton. Essentially, SUVs, pickup trucks, and minivans will ultimately be held to the same requirements as ordinary cars on a nationwide basis, keeping pace with California's vanguard clean air initiatives.

Concurrently, the federal EPA will direct oil refiners to reduce the amount of sulfur in gasoline by 90 percent (to an average of 30 parts per million). This will make it easier for carmakers to meet the new emission standards because of the adverse effect of sulfur on catalytic converters.

Reducing pollution today will result in ongoing benefits for decades into the future. ❖

Workshop (continued from page 1)

managers David Amlin, Terry Ford, George Adelsperger, and Mike Vanderlaan briefed the group on numerous aspects of the program. Among the topics covered were:

- Equipment requirements, certification, and remote sensing.
- Vehicle certification process and electronic transmission.
- Technician licensing and training.
- Key program enforcement elements.

Question and answer periods followed each of the presentations. A tour of the Chula Vista Referee Center was held on the second day of the workshop, which included a demonstration of the BAR-97 Smog Check testing equipment and a remote sensing demonstration conducted by Paul Hedglin of BAR's Engineering Division.

"The purpose of this workshop was to help our neighbors south of the border to better understand the goals and responsibilities of the California Smog Check Program," Dorais said. "The information will hopefully lead to implementation of emissions control laws and a vehicle inspection program in various cities in Baja California."

HISTORICAL TEST DATA ACCESSIBLE ON EIS MACHINES



ccess to historical data from tests conducted using a BAR-97 Emission Inspection System (EIS) is available for review at individual Smog Check stations, according to BAR's Engineering

"On the BAR-97, station owners and technicians have the ability to review tests conducted on vehicles at their stations," said Engineering Manager David Amlin. "There is anywhere from one test to hundreds of past tests that can be reviewed depending upon which type of system a station is using."

While BAR-97 specifications require the units to be able to store 1,000 tests, they do not require the analyzers to display the completed tests. Because manufacturers were not specifically required to provide a history of completed tests, the number of tests available for recall and display is different for each unit.

Here's how to access the historical test data on the BAR-97 EIS for each manufacturer:

 $\ensuremath{\mathsf{SPX}}$ — An unknown number of previously completed tests can be viewed:

→ From the *Test Menu*, select item number 2, called *Reprint VIR*. It will reprint the last Vehicle Inspection Report (VIR) completed.

Worldwide — An unknown number of previously completed tests is available, but it is estimated that more than 40 can be viewed:

→ From the *Main Menu*, select item number 9, *Recall Previous Test*, highlight the VIR you wish to review, and press print.

Snap-On — It is estimated that more than 100 previously completed tests can be viewed:

Select from the *Main Menu*, item number 4, *Recall Previous Vehicle Tests*. Choose the test you wish to review and press print.

ESP — An unknown number of previously completed tests can be viewed:

→ From the *Main Menu*, select *Inspection Menu*, then select *Recall Vehicle Information*. You will be able to reprint the last test completed. Or, go to *Recall Vehicle Information* and enter the license number of the vehicle you wish to review.

The process to review previously completed tests on the BAR-90 TAS units is similar. Here's how to get access to the data for each manufacturer's unit:

Sun — This unit will print only the last VIR produced and the outcome of the last test:

→ From the *Main Menu*, select *Reprint Last VIR*.

ESP — About 25 previously completed vehicle test records are available on the unit:

→ From the *Main Menu*, go to *Inspection Menu* and select *Recall Vehicle Information*.

Allen — The exact number of previously completed tests available on this unit is unknown, but is believed to be more than 40:

→ From the *Main Menu*, select *Smog Check Menu* and choose item number 5, *Reprint VIR*.

Bear — This unit provides only the last VIR and the outcome of the last test conducted:

→ From the *Smog Check Menu*, select item number 3, *Reprint Last VIR*. ❖

Test-Only (continued from page 1)

"The data are then sorted to determine which vehicle classes (make, model, year, engine family) are most likely to fail their Smog Check inspections, especially at Gross Polluter levels," Amlin added.

"There is no single factor that identifies a vehicle that is likely to fail. A vehicle may be directed to a Test-Only station even if it has never failed a previous test, including its last one." This can happen when the vehicle belongs to a class that has a high probability of failure.

There are several steps involved in the process of selecting which vehicles in each Enhanced Area of the state are sent to Test-Only stations each month.

Using Department of Motor Vehicles (DMV) data, the number of vehicles in each Enhanced Area of the state is determined. It should be noted that vehicles four model-years old and newer are included in the program count, because they are part of the Smog Check Program, even though they are currently exempt from the biennial inspection.

Each month, all vehicles in each Enhanced Area are put through a HEP model and ranked as to their likelihood of failing a Smog Check inspection. After the vehicles have been ranked by likelihood of failure, they are ranked again to establish the probability of failure, and assigned an "F Prob."

"From that list, we take 2 percent from each of the 14 counties with Enhanced Areas to use as a baseline," Amlin said. "The remaining 'F Prob' vehicles are separated by county, and those classes most likely to fail in each county are sent to Test-Only stations."

For example purposes only, if there were a total of 4-1/2 million vehicles in Los Angeles County, half of them (or 2,225,000) would be subject to Smog Check every year. In the Test-Only referral process, after the ranking procedures described above are completed, BAR would randomly select 2 percent (or 3,750 vehicles) and send them to Test-Only stations. From the remaining vehicles, another 24,375 would be directed to Test-Only each month in L.A. County.

Obviously, pretesting a vehicle will not prevent it from being sent to a Test-Only station because it would have no impact on the process BAR uses to determine which vehicles will be directed, since it focuses on vehicle classes rather than specific vehicles.

However, if a vehicle has had proper repair over the years, it will likely pass at a Test-Only station Census 2000

The Census is Coming. Please Answer the Census by Mail. Every 10 years the Census Bureau is required by the U.S. Constitution to count every person in the United States. In mid-March, you will be mailed the official census questionnaire, and April 1, 2000, is Census Day. Census information is 100% confidential. The Bureau is strictly prohibited from sharing information with any other individuals or organizations, public or private. Also, California communities could lose over \$3 billion in federal tax revenue during the next decade if Californians do not respond. Please mail back your census questionnaire promptly. For more information, visit the Census Bureau's website at www.census.gov, or for information about temporary census jobs call (888) 325-7733.

#

The Bottom Line as of January 1, 2000

%

Technician Data

- 108 Cut score on the current smog exam.
- **70.81** Percent of technicians passing EA Smog Check exam in December.
- 8,158 Technicians completing BAR-97 eight-hour Transition Training.
- 8,902 Advanced (EA) technicians licensed.
- 4,522 Basic (EB) technicians licensed.

Station Data

- 4,881 Test & Repair Stations statewide.
- 1,907 Gold Shield Guaranteed Repair (GSGR) stations statewide.
 - **340** Gross Polluter Certification (GPC) stations statewide.
 - **394** Test-Only stations statewide.
 - **517** Test-Only lanes statewide.

Consumer Assistance Program Data

- 82 GPC stations providing Repair Assistance.
- 3,794 Vehicles repaired.
 - 31 Dismantler sites for vehicle retirement.
- 1,254 Vehicles retired.



even if its vehicle class falls into the HEP category. Those that have not been properly maintained may not pass at a Test-Only station.

Motorists who are required to have their vehicle's Smog Check inspection performed at a Test-Only station are notified by the DMV 95 days before their registration is due.

Included with the DMV renewal notice, which indicates that the Smog Check inspection must be done at a Test-Only station, is a Smog Check Program insert telling motorists to call the Department of Consumer Affairs' toll-free information line at (800) 952-5210 to find a conveniently located Test-Only station. Or, motorists with Internet access can go to BAR's website at <code>www.smogcheck.ca.gov</code> and click on the list of Test-Only stations. The motorist may then call the Test-Only station and make an appointment for a Smog Check inspection.

As the name implies, Test-Only stations are authorized to conduct Smog Check inspections but are prohibited from making *any* diagnosis or

vehicle repairs, except for pre-inspection oil changes and lubrication services.

If the vehicle fails at a Test-Only station, it must be repaired. However, the Test-Only technician cannot make referrals to another repair station. Consumers may choose a Test & Repair or Gross Polluter Certification (GPC) pilot station from a BAR-approved list that is posted at the Test-Only station. They are instructed to take the Vehicle Inspection Report (VIR) showing the results of the test conducted at the Test-Only station with them when they arrive at the Test & Repair or GPC station.

"Once the consumer arrives with the vehicle for repair, service writers and technicians should look carefully at the VIR provided by the Test-Only station," Amlin said. "The next step is to begin a complete diagnosis before attempting repairs."

Once the diagnosis and repair is complete, the vehicle must be retested at a Test-Only station for certification. •

Tech Tips & Causes of Disciplinary Actions Are Top Reader Survey Requests

esponses to the last Reader Survey (July 1999 issue) spoke out loud and clear for two things . . . a "tech tip" column and information concerning the causes of disciplinary actions.

New Smog Check Advisory Chat Page

In response to your request for tech tips, a new feature is being introduced in the *Smog Check Advisory* where you can ask tough questions, share technical tips, and reference handy information. Look for your inquiries and solutions on the new Smog Check Advisory Chat Page each month.

Simply submit your questions or tips to us by mail, fax, or email... and watch for them in print. Let's hear from you!

By Mail:

BAR Communications Team Smog Check Advisory Chat Page 400 R Street, Suite 3060 Sacramento, CA 95814

By Fax:

916-445-8796 Attn: Smog Check Advisory Chat Page

By Email:

scachatpage@dca.ca.gov


Causes of Disciplinary Actions

When the Enforcement Division was asked about the nature and scope of disciplinary actions, Wayne Ramos, Program Manager I, stated, "You name it, and we've probably found it! From stations that resort to using 'low emission' vehicles in order to certify other vehicles that are not in emission compliance, to those that fabricate sophisticated tach simulations to manipulate a vehicle's RPM readings, or create counterfeit Vehicle Inspection Reports in an effort to circumvent Smog Check requirements, there is no end to the misapplied 'ingenuity' of

some technicians. And these are just a few examples of the most serious Smog Check offenses."

Ramos further advised, "The variety of violations in disciplinary cases goes far beyond the highly publicized 'clean piping' cases, however. There are also a high number of instances involving improper and incomplete inspections. A few

examples are failing to perform ignition timing checks; failing to recognize or even check for missing, modified, or disconnected emission control systems or components;



When a technician or station gets "busted," there is no hard and fast unwavering penalty for any specific violation or combination of violations. The facts and circumstances of each case (mitigation, aggravation, disciplinary history, as well as the magnitude and severity of the violations) are considered in the imposition of penalties. There is a wide range of penalties that may be imposed in disciplinary cases . . . from issuance of a citation, to public reproval, probation, suspension, outright revocation of licensure, and any combination in between. Generally, acts of "clean piping" will almost certainly result in revocation of the station's and technician's licenses. Performing improper or incomplete inspections will generally draw penalties ranging from issuance of a citation to

probation with a period of suspension. And, in extreme cases, these acts will result in outright revocation of licenses. In addition to the disciplinary penalties imposed on licenses, monetary fines, reimbursement of investigative costs, and restitution to victims may also be imposed. Monetary penalties have ranged from as little as \$250 to more than \$100,000.

Since the decisions rendered in disciplinary actions are often based on a multitude of charges and allegations, to itemize each infraction for every disciplined licensee in the Smog Check Advisory would be impractical.

However, more detailed disciplinary action information will become available in the near future on the BAR website. That portion of the website is currently "under construction." An announcement will be made when it is activated.

To guide Administrative Law Judges in proposing penalties, and to inform licentiates of the potential impact on their licenses of improper or illegal behavior, the Bureau has adopted and published its *Guidelines for Disciplinary Penalties and Terms and Conditions of Probation* (revised May 1997). Copies may be obtained from any BAR field office or through the DCA/BAR website: www.smogcheck.ca.gov. *



Correction

A story in the January edition of the *Smog Check Advisory* erroneously said that the BAR-97 analyzer contains specific codes for the technician to use when a test must be aborted. The story should have said that the BAR-90, not the BAR-97 analyzer, contains codes to use when a test is aborted.

Disciplinary Actions

Northern California

prosecution. (10/07/99)

AUTOTECH MOTOR SERVICE—San Mateo Sami R. Haddad, Owner *Order:* ARD registration revoked, stayed, and placed on three years' probation. Smog Check Station license revoked. Further ordered to report to BAR as directed and reimburse BAR \$4,000 for costs of investigation and

HIDEKI JOE WATANABE—Hayward *Order:* Basic Area Smog Check Technician license revoked. (10/07/99)

JOHN ZAREFAKIS—Lodi Order: Advanced Emission Specialist Technician license revoked. (10/22/99)

WAYNE'S SMOG INSPECTION—Oakley Willard A. Wayne, Owner *Order:* ARD registration permanently invalidated, stayed, and placed on three years' probation. Smog Check Station license revoked, stayed, placed on three years' probation, and suspended for 30 days. Further ordered to report to BAR as directed and reimburse BAR \$3,500 for costs and expenses of investigation. (10/26/99)

JEFFREY JOHN WAYNE—Oakley *Order:* Advanced Emission Specialist Technician license revoked, stayed, placed on three years' probation, and suspended for 30 days. (10/26/99)

ANTHONY RICHARD BERTOLINI—Sebastopol *Order:* Basic Area Smog Check Technician license revoked. (10/27/99)

Southern California

TURBO PERFORMANCE—Van Nuys
Robert Anthony Serra, Owner/Technician
Order: ARD registration permanently invalidated.
Smog Check Station license and Advanced
Emission Specialist Technician license revoked.
Further ordered to reimburse
BAR \$13,000 for costs of investigation and prosecution. (10/07/99)

CITY AUTO REPAIR—San Diego
Joseph Michael Meram, Owner/Technician
Order: ARD registration revoked, stayed, and
placed on two years' probation. Smog Check
Station license revoked, stayed, placed on two
years' probation, and suspended for 30 days.
Advanced Emission Specialist Technician license
revoked, stayed, and placed on two years'
probation with 30 days' suspension. Further
ordered to report to BAR as directed, successfully
complete a BAR-approved training course in
diagnosis and repair of emission systems failures
and engine performance and automotive-related
studies, and reimburse BAR \$7,150. (10/07/99)

KING SMOG—Hawthorne Bau Van Nguyen, Owner *Order:* ARD registration and Smog Check Station license revoked. (10/07/99)

THUAN DUC VO—Gardena *Order:* Advanced Emission Specialist Technician license revoked, stayed, placed on three years' probation, and suspended for one year plus additional time if necessary to take and pass licensure examination for Advanced Emission Specialist Technician license. Also ordered to take

and pass with a grade of C or better six semester units of junior college level vocational training in the area of diagnosis and repair of improperly functioning motor vehicle emission control systems. Further ordered to report to BAR as directed. (10/07/99)

BAJA SMOG—Los Angeles George Sanchez Guerrero, Owner/Technician— Monterey Park

Order: ARD registration and Smog Check Station license revoked. Advanced Emission Specialist Technician license revoked, stayed, placed on five years' probation, and suspended for 60 days. Further ordered to report to BAR as directed and reimburse BAR \$5,000 for legal and investigative costs. (10/08/99)

VALLEYS UNION, INC.—North Hollywood Norallah F. Amirian, President *Order:* Smog Check Station license revoked, stayed, placed on two years' probation, and suspended for 45 days. (10/13/99)

SULTAN'S AUTOMOTIVE SERVICE CENTER—San Luis Obispo

Sultan Yeaqub Ahmed, Owner/Technician *Order:* ARD registration, Smog Check Station license, and Advanced Emission Specialist Technician license revoked. (10/14/99)


ROBERTO GARCIA CARDENAS—Fontana *Order:* Advanced Emission Specialist Technician license revoked, and any other license issued in the name of Roberto Garcia Cardenas revoked or suspended. (10/14/99) ❖

Voided Warranty on Improper Cat Replacement?

he Bureau of Automotive Repair's newly released *Smog Check Inspection Manual* states that a vehicle must be in fuel control before replacing a catalytic converter (see page 100, #2). "Installing a replacement catalytic converter to get the vehicle to pass the test on a vehicle that has failed the tailpipe portion of the inspection, without first repairing the actual cause of the failure, may void the warranty on the converter," advises Wayne Brumett of BAR's Standards and Training Branch.

For example, the website (www.car-sound.com) of Car Sound, an aftermarket catalytic converter manufacturer, states, "Your catalytic converter should have never failed. If it did, then you have

a problem." The manufacturer lists several reasons for catalytic converter failure; chief among them is an out-of-tune engine. Further, the manufacturer advises, "Any time an engine is operating outside proper specifications, unnecessary wear and damage may be caused to the catalytic converter as well as to the engine



Catalytic Converter

itself. The damage is often the result of an incorrect air/fuel mixture, incorrect timing, or misfiring spark plugs." Car Sound warns: "... the warranty that comes with a new replacement catalytic converter does not cover the type of damage listed above."

BAR does not consider it an accepted trade practice to replace a catalytic converter on a vehicle that fails a tailpipe inspection, unless the cause of the emission failure is properly diagnosed and repaired. Without proper repairs, the fix would be temporary and deprive not only the vehicle owner of the benefits of improved performance, but all of us of cleaner, healthier air.
* (See related article on page 7.)

CAP Pays Off With More Effective Repairs

he Bureau of Automotive Repair's new Consumer Assistance Program (CAP), formerly known as the Low-Income

Repair Assistance Program, or LIRAP, is having a positive effect on the quality of repairs being made by participating shops, according to reviews of repair invoices and work orders.

Although the number of cars repaired under CAP since it was implemented statewide on March 31, 1999, is small so far—slightly more than 3,200 as of November—the types of repairs being done are ones that will have a long-term benefit for consumers whose cars received state repair assistance, and for all Californians with improved air quality.

"Technicians at shops participating in CAP are conducting a full diagnosis to make the repairs that are in the best interest of the consumer and the program," said BAR's Deputy Chief Patrick Dorais. "They are doing what they have been taught."

Data are beginning to show that CAP technicians are identifying and making a significant number of upstream repairs—those in front of

the catalytic converter (CAT)—before they rush to CAT replacement as the fix. Numerous studies have shown that premature replacement of the CAT is often a costly short-term fix for the consumer, the car, and air quality. (See related article on page 6.)

Upstream repairs include items such as the ignition system, fuel system, and emissions control systems, which also include the fuel evap, exhaust gas recirculation (EGR), and air injection systems.

Examination of the repair data on participating CAP vehicles clearly shows a drop in the number of CAT replacements to about 20 percent from more than 38 percent, according to Dorais.

Other statistics show that the total average repair cost in CAP through November 1999 was \$461.17. Of that amount, consumers spent an average of \$108.62, while the state spent \$352.55. In addition, nearly 59 percent of the vehicles repaired were Gross Polluters. The result is an overall estimated emissions reduction of 338.61 tons.

Under CAP, consumers with an income level of 175 percent of the federal poverty level (about

\$29,000 for a family of four) are eligible for repair assistance. Consumers are required to make a co-payment of \$75 toward the vehicle's repair, and the work must be done at a Gold Shield Gross Polluter Certification station that has elected to participate in the CAP program.

Originally implemented on November 5, 1998, in Sacramento as the Low-Income Repair Assistance Program, CAP was expanded statewide on March 31, 1999. Initially, consumers were required to make a co-payment of \$250 toward repairs, but that was reduced to the current \$75 co-payment on May 3, 1999.

"Our findings are showing that consumers do want to make the kinds of repairs that produce long-term benefits for them and the air," Dorais said.

"As we progress, consumers on average are voluntarily spending more than the required \$75 to make the full and complete repairs needed in cases where the state's maximum payment of \$450 has been reached."

SMOG CHECK STATION CITATIONS



- * Stations that have had their Gold Shield Guaranteed Repair (GSGR) certification withdrawn (none reported).
- ** Stations that have had their Gross Polluter Certification (GPC) Pilot authority withdrawn (none reported).
- *** Stations that have had their GPC and Repair Assistance authority withdrawn (none reported).



State of California Gray Davis, Governor

California Department of Consumer Affairs Kathleen Hamilton, Director

Bureau of Automotive Repair Douglas E. Laue, Chief 10240 Systems Parkway Sacramento, CA 95827

BAR FIELD OFFICE PHONE NUMBERS

Bakersfield	. (661)	833-6304
Canoga Park	. (818)	596-4400
Culver City	. (310)	410-0024
Fresno	. (559)	445-5015
Fullerton	. (714)	680-7851
Oceanside	. (760)	439-0942
Richmond	. (510)	243-9410
Riverside	. (909)	782-4250
Sacramento	. (916)	255-4200
San Jose	. (408)	277-1860
South El Monte	. (626)	575-6934
DCA Cashiering	. (916)	322-7002
DCA Licensing	. (916)	322-4000
ET Help Desk	. (916)	255-4476
MCI	(800)	731-SMOG
(Then press 5 for to	echnica	al support)

Consumer Assistance and Referee Center ... (800) 622-7733 DCA HOTLINE (800) 952-5210

Smog Check Advisory February 2000

Little Scoops...

- Some minor adjustments to the new Smog Check Inspection Manual are in the works. They will be included in an upcoming edition of the Smog Check Advisory with instructions on how shops can insert them directly into the binders holding the new manuals.
- Current law exempts vehicles four modelyears old and newer from biennial (every
 other year) smog inspections. Starting with
 DMV vehicle registrations due January 1,
 2000, and later, all 1997, 1998, 1999, and
 2000 model-year vehicles are exempted from
 biennial smog inspections. However, these
 newer vehicles are required to have a smog
 inspection upon change of ownership and
 initial registration as a used vehicle in
 California. The exemption is based on the
 model-year of the vehicle, not the date of
 purchase.
- Did you know? . . . to view past and present issues of the Smog Check Advisory, visit our website at www.smogcheck.ca.gov. Just scroll to the bottom of the home page, click on "Download BAR Forms, Newsletters and Fact Sheets," and then select "Smog Check Advisory newsletters." You'll find two and a half years' worth of our monthly smog publication, as well as many other useful publications.
- Automotive Service Excellence (ASE) technician certifications now have different expiration dates, depending on when an exam was passed. Certifications for exams passed in May will continue to expire in the month of July, five years later. However, ASE certifications issued as a result of passing November exams will now have January expiration dates. For example, certifications

- issued from May 1999 exams will expire in July 2004, and certifications issued as a result of exams passed in November 1999 would be valid to January 2005.
- Additional locations where new computerized technician examinations can be held are being explored. The new test sites are expected to be open six days a week, Monday through Saturday.
- The Quality Assurance Program is continuing to evaluate shops based on four major criteria—a low vehicle failure rate, the number of aborted tests, reported repair costs, and technician competency, according to BAR's Smog Check Enforcement Manager Mike Vanderlaan.

U.S. Postage PAID Oakland, CA Permit No. 2101

Bulk Rate